

NOTES:

1. 2" BRASS PIPE AND FITTINGS SHALL BE USED FOR AIR RELEASE ASSEMBLY.
2. ALL DUCTILE IRON MAINS, SIX INCHES IN DIAMETER AND LARGER, MAY BE TAPPED WITHOUT SADDLES. WHERE PVC MAINS ARE PERMITTED BY LOCALITIES, THE CONNECTION TO A PVC MAIN MUST BE TAPPED WITH A SADDLE. TAPPING SADDLES TO BE INSTALLED IN ACCORDANCE WITH THE MANUFACTURES SPECIFICATIONS. ALL SADDLES TO BE STAINLESS STEEL OR EPOXY COATED.
3. ALL BRASS FITTINGS SHALL HAVE IRON PIPE THREADS.
4. BRASS PIPE SHALL HAVE MALE IRON PIPE THREADS AT EACH END.
5. THE CORPORATION STOPS SHALL BE MANUFACTURED WITH AWWA/CC TAPERED INLET THREADS.
6. CORPORATION STOPS JOINING TO EXISTING GALVANIZED PIPING OR PROPOSED BRASS PIPE SHALL HAVE FEMALE IRON PIPE THREADS.
7. FOR CORPORATION STOPS JOINING TO GALVANIZED OR BRASS PIPING, USE FORD METER BOX CO., MODEL FB1600.

MANUAL AIR VENT ASSEMBLY

NOT TO SCALE

<i>REFERENCE</i> 200,801,803	<i>CATEGORY</i> WATER & SANITARY	<i>DATE</i> 12/10	<i>SHEET No.</i> 2 OF 2	<i>DETAIL No.</i> WS_03
---------------------------------	-------------------------------------	----------------------	----------------------------	----------------------------